

ANNOTATED REPLACEMENT SHEET



In Figure 2, element 73 has been added to depict the hook and Loop fastener of CLAIMS 12, 26, 13, and 27 and as described AT PP 10-11, LIS - 10 of the Specification.

ANNOTATED REPlacement Sheet







Fig 8





CANCELLED






FIG. 15




FIG. 16:

CANCELLED






FIG 20 14

BOTH Figures renumbered. See Remarks.







FIG 28 15








REPLACEMENT SHEET









Fig 8

- CANCELLED





CANCELLED






FIG. 15




FIG. 16




Fig. 14




Fig. 15

SHEET

REPLACEMENT

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER: _____

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.